

RECEIVED
AUG 2 3 2002
TECH CENTER 1600/2900
09 624885




FIG.1B




FIG.2A



FIG.2B





6673604 3/7

FIG.3








FIG.4
Diastolic Pressure-Volume











AUG 2 3 2002 TECH CENTER 1600/2900

6/7



FIG.7A






FIG.7B





AUG 2 3 2002 TECH CENTER 1600/2900



7/7

Decreased Ventricular Remodeling




FIG.8B

